

Dorman Bridge

HICK02

GENERAL DATA

structure no.: 090001.0	city/town: 1.6 miles south of Hermitage
county: Hickory	feature inters.: Pomme de Terre River
	cadastral grid: S34/35, T37N, R22W
	highway route: County Road 90
	highway distr.: 8
	current owner: Hickory County

STRUCTURAL DATA

superstructure: steel, 12-panel, pin-connected Parker through truss, with steel stringer approach spans	
substructure: concrete abutments, wingwalls and spill-through pier	
span number: 1	condition: fair
span length: 200.0'	alterations: moved to current location, 1933-34
total length: 404.0'	floor/decking : timber deck over steel channels
roadway width: 13.7'	other features: upper chord and inclined end post: 2 channels with cover plate and lacing; lower chord: 2 punched rectangular eyebars; vertical: 2 angles with lacing; diagonal: 2 punched rectangular eyebars; counter: square eyebar with turnbuckle; lateral bracing: round rod with threaded ends; strut: 2 angles; floor beam: I-beam, field bolted to vertical; guardrail: 2 angles

HISTORICAL DATA

erection date: c1920; moved c1933
erection cost: unknown
designer: unknown
fabricator : Illinois Steel Company, Chicago IL
contractor: unknown

references: Missouri Highway and Transportation Department, Structure Inventory and Appraisal: Structure Number 090001.0; Hickory County Court Record, Book S: page 37 (7 August 1933), page 49 (1 September 1933), page 51 (2 September 1933), page 57 (2 October 1933), page 170 (7 November 1934), page 174 (3 December 1934) - located at Hickory County Courthouse, Hermitage MO; field inspection by Clayton Fraser, 29 January 1990.

sign. rating: 35
evaluation: NRHP non-eligible (long-span example of pinned Parker through truss construction, moved and inadequately documented)

inventoried by: Clayton B. Fraser 28 February 1990