

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Pennsylvania [42] Chester County [029] Tredyffrin [77344] 1.5MI.NE OF PAOLI 24B06 40-03-25 = 40.056944 075-27-41 = - 75.461389
 157236041700010 Highway agency district: 6 Owner Railroad [27] Maintenance responsibility Railroad [27]
 Route 0 HOWELLVILLE ROAD Toll On free road [3] Features intersected NORFOLK SOUTHERN CORP
 Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi
 1 Truss - Thru [10] 0 Other [00] Year built 1897 Year reconstructed 1992
 Skew angle 20 Structure Flared
 Historical significance Historical significance is not determinable at this time. [4]
 Total length 28.7 m = 94.2 ft Length of maximum span 27.1 m = 88.9 ft Deck width, out-to-out 6.1 m = 20.0 ft Bridge roadway width, curb-to-curb 5.8 m = 19.0 ft
 Inventory Route, Total Horizontal Clearance 5.8 m = 19.0 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft
 Deck structure type Wood or Timber [8]
 Type of wearing surface Bituminous [6]
 Deck protection
 Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi Method to determine inventory rating Allowable Stress(AS) [2] Inventory rating 10.9 metric ton = 12.0 tons
 Method to determine operating rating Allowable Stress(AS) [2] Operating rating 17.2 metric ton = 18.9 tons
 Bridge posting Design Load

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of replacement [2]
Condition ratings - superstructure	Fair [5]	Appraisal ratings - roadway alignment	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge not over waterway. [N]		
Channel and channel protection	Not applicable. [N]		
Appraisal ratings - water adequacy	N/A [N]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	28.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	October 2008 [1008]	Designated inspection frequency	24 Months
Underwater inspection	Unknown [N00]	Underwater inspection date	
Fracture critical inspection	Unknown [N00]	Fracture critical inspection date	
Other special inspection	Every two years [Y24]	Other special inspection date	