

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Kent County [081]	Algoma [01160]	.50 MI N OF 10 MILE RD	43-07-26 = 43.123889	085-39-02 = - 85.650556
41200081000B010	Highway agency district 3	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	PINE ISLAND DRIVE	Toll On free road [3]	Features intersected	ROGUE RIVER	
Design - main Concrete [1]	Design - approach	Kilometerpoint 914.3 km = 566.9 mi	Year built 1924	Year reconstructed N/A [0000]	
1	Girder and floorbeam system [03]	0 Other [00]	Skew angle 0	Structure Flared	
		Historical significance	Bridge is on the NRHP. [1]		
Total length 30.4 m = 99.7 ft	Length of maximum span 28.3 m = 92.9 ft	Deck width, out-to-out 6.1 m = 20.0 ft	Bridge roadway width, curb-to-curb 6.1 m = 20.0 ft		
Inventory Route, Total Horizontal Clearance 6 m = 19.7 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.8 km = 0.5 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	17.4 metric ton = 19.1 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	29 metric ton = 31.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18+Mod / HS 20+Mod [6]	

Functional Details

Average Daily Traffic	3157	Average daily truck traffi	0	%	Year	2004	Future average daily traffic	5370	Year	2024
Road classification	Minor Collector (Rural) [08]	Lanes on structure	2	Approach roadway width	7.9 m = 25.9 ft					
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]		Bridge median					
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control						
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	500000	Roadway improvement cost	100000						
	Length of structure improvement	200 m = 656.2 ft		Total project cost	600000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - superstructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Satisfactory [6]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for assessed or calculated scour condition. [5]"/>		
Channel and channel protection	<input type="text" value="Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="55.8"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Traffic safety features - transitions	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="October 2009 [1009]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>