

HistoricBridges.org - National Bridge Inventory Data Sheet

2014 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

New Jersey [34]	Sussex County [037]	Unknown [00000]	OFF OF NPS ROAD 615 (WALP)	41-09-25.80 = 41.157167	074-52-37.70 = -74.877139
4320040P0000000	Highway agency district 0	Owner National Park Service [66]	Maintenance responsibility	National Park Service [66]	
Route 0		MAIN STREET	Toll On free road [3]	Features intersected	FLAT BROOK
Design - main	Steel [3]	Design - approach		Kilometerpoint	0 km = 0.0 mi
1	Truss - Thru [10]	0	Other [00]	Year built	1889
				Year reconstructed	2013
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is possibly eligible for the NRHP. [3]
Total length	20.9 m = 68.6 ft	Length of maximum span	20.4 m = 66.9 ft	Deck width, out-to-out	3.7 m = 12.1 ft
Inventory Route, Total Horizontal Clearance	3.6 m = 11.8 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Open Grating [3]				
Type of wearing surface					
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	4.6 metric ton = 5.1 tons
0.8 km = 0.5 mi	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	6.3 metric ton = 6.9 tons
	Bridge posting		Design Load	Other [C]

Functional Details

Average Daily Traffic	370	Average daily truck traffi	10	%	Year	2011	Future average daily traffic	444	Year	2031
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	4.6 m = 15.1 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost

0

Roadway improvement cost

0

Length of structure improvement

20.7 m = 67.9 ft

Total project cost

0

Year of improvement cost estimate

2007

Border bridge - state

Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Very Good [8]		
Scour	Countermeasures have been installed to mitigate an existing problem with scour. [7]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present minimum criteria [6]	Status evaluation	
Pier or abutment protection		Sufficiency rating	24.2
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends			
Inspection date	November 2013 [1113]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	November 2013 [1113]
Other special inspection	Not needed [N]	Other special inspection date	