The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information						40-08-00 =	080-00-21 = -
Pennsylvania [42] Washington County [125]		Somerset [71792] SOMERSET TOWNSHIP		40.133333	80.005833		
620917016000880 Highway a	gency district 12	Owner State Highway	Agency [01]	Maintenance	responsibility	State Highway Ag	ency [01]
Route 917	R 0917	Toll On fre	ee road [3]	eatures intersec	sted SR 0070		
Design - main  Steel [3]  Girder and floorbeam system	Design - approach  n [03] 0 Other [0]	00]	Kilometerpoint 100 Year built 1949 Skew angle 16 Historical significance	Structure F	constructed N/A	[0000] he NRHP. [5]	
Total length 25.9 m = 85.0 ft Inventory Route, Total Horizontal Clear	Length of maximum spar ance 8.5 m = 27.9 ft	24.4 m = 80.1 ft  Curb or sidewalk w	Deck width, out-to-out vidth - left $0.2 \text{ m} = 0.7$			dway width, curb-to-c	8.5 m = 27.9 ft 1.8 m = 5.9 ft
Deck structure type	Concrete Cast-in-Place	e [1]				_	
Type of wearing surface	Bituminous [6]						
Deck protection							
Type of membrane/wearing surface							
Weight Limits							
Bypass, detour length  1 km = 0.6 mi  Method to determine inventory rating  Method to determine operating rating		Load Factor(LF) [1]  Load Factor(LF) [1]		entory rating erating rating	31.8 metric ton = 52.6 metric ton =		
Bridge postin	. 0	, , , -		0 0	32.6 Hetric torr =	- J1.7 (UIIS	

Functional Details	
Average Daily Traffic 1112 Average daily tr	uck traffi 9 % Year 2010 Future average daily traffic 1641 Year 2012
Road classification Major Collector (Rural) [07]	Lanes on structure 2 Approach roadway width 7.9 m = 25.9 ft
Type of service on bridge Highway-pedestrian [5]	Direction of traffic 2 - way traffic [2]  Bridge median
Parallel structure designation No parallel structure	exists. [N]
Type of service under bridge Highway, with or without	ut ped Lanes under structure 8 Navigation control Not applicable, no waterway. [N]
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A
Minimum navigation vertical clearance, vertical lift brid	Minimum vertical clearance over bridge roadway 99.99 m = 328.1 ft
Minimum lateral underclearance reference feature H	ghway beneath structure [H]
Minimum lateral underclearance on right 2.9 m = 9.5	ft Minimum lateral underclearance on left 0 = N/A
Minimum Vertical Underclearance 4.34 m = 14.2 ft	Minimum vertical underclearance reference feature Highway beneath structure [H]
Appraisal ratings - underclearances Basically intoler	able requiring high priority of corrrective action [3]
Repair and Replacement Plans	
Type of work to be performed	Work done by Work to be done by owner's forces [2]
Bridge rehabilitation because of general structure deterioration or inadequate strength. [35]	Bridge improvement cost 0 Roadway improvement cost 0
deterioration of madequate strength. [55]	Length of structure improvement 33.5 m = 109.9 ft Total project cost 0
	Year of improvement cost estimate
	Border bridge - state  Border bridge - percent responsibility of other state
	Border bridge - structure number

Inspection and Sufficiency							
Structure status Open, no res	striction [A]	Appraisal ratings - structural	Somewhat better than minimum adequacy to tolerate being left in place as is [5]				
Condition ratings - superstructur	Fair [5]	Appraisal ratings - roadway alignment  Appraisal ratings -	Better than present minimum criteria [7]  Somewhat better than minimum adequacy to tolerate being left in place as is [5]				
Condition ratings - substructure	Fair [5]						
Condition ratings - deck	Fair [5]	deck geometry	13 [0]				
Scour	Bridge not over waterway. [N]						
Channel and channel protection	Not applicable. [N]						
Appraisal ratings - water adequac	vy N/A [N]		Status evaluation	Functionally obsolete [2]			
Pier or abutment protection			Sufficiency rating	71.6			
	if structure is not a culvert. [N]						
Traffic safety features - railings							
Traffic safety features - transition  Traffic safety features - approach							
Traffic safety features - approach							
Inspection date March 2008 [		ction frequency 24	Months				
	Not needed [N]	Underwater inspec					
·							
Other special inspection  Not needed [N]  Other special inspection date							