

# HistoricBridges.org - National Bridge Inventory Data Sheet

2010 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

## Basic Information

Michigan [26]	Kent County [081]	Vergennes [81920]	0.25 MI NE OF LIN LK AV	42-57-56 = 42.965556	085-21-03 = - 85.350833
41322H00007B010	Highway agency district 3	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0		BURROUGHS ST	Toll On free road [3]	Features intersected FLAT RIVER	
Design - main	Steel [3]	Design - approach		Kilometerpoint	44.1 km = 27.3 mi
1	Truss - Thru [10]	0	Other [00]	Year built	1995
				Year reconstructed	N/A [0000]
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is not eligible for the NRHP. [5]
Total length	38.1 m = 125.0 ft	Length of maximum span	36.5 m = 119.8 ft	Deck width, out-to-out	13.4 m = 44.0 ft
Inventory Route, Total Horizontal Clearance	8.1 m = 26.6 ft	Curb or sidewalk width - left	1.5 m = 4.9 ft	Curb or sidewalk width - right	1.5 m = 4.9 ft
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection	Epoxy Coated Reinforcing [1]				
Type of membrane/wearing surface					

## Weight Limits

Bypass, detour length	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	31.7 metric ton = 34.9 tons
0.6 km = 0.4 mi	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	52.9 metric ton = 58.2 tons
	Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18+Mod / HS 20+Mod [6]

### Functional Details

Average Daily Traffic	677	Average daily truck traffi	5	%	Year	2003	Future average daily traffic	1150	Year	2023
Road classification	Minor Collector (Rural) [08]		Lanes on structure	2		Approach roadway width	9.1 m = 29.9 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost

Roadway improvement cost

Length of structure improvement

Total project cost

Year of improvement cost estimate

Border bridge - state

Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - superstructure	<input type="text" value="Very Good [8]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - substructure	<input type="text" value="Very Good [8]"/>	Appraisal ratings - deck geometry	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - deck	<input type="text" value="Very Good [8]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for assessed or calculated scour condition. [5]"/>		
Channel and channel protection	<input type="text" value="Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="83.6"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="November 2009 [1109]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>

# HistoricBridges.org - National Bridge Inventory Data Sheet

1992 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

## Basic Information

Michigan [26]	Wayne County [163]	Unknown [00000]	BELLEVILLE	S/I-94		
82200110000B010	Highway agency district	9	Owner	County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]
Route	2057		BELLEVILLE ROAD	Toll	On free road [3]	Features intersected
						HURON RIVER
Design - main	Steel [3]	Design - approach		Kilometerpoint		
1	Truss - Thru [10]	0	Other [00]	Year built	1924	Year reconstructed
						1953
				Skew angle	0	Structure Flared
				Historical significance	Bridge is on the NRHP. [1]	
Total length	37.5 m = 123.0 ft	Length of maximum span	36.6 m = 120.1 ft	Deck width, out-to-out	9.1 m = 29.9 ft	Bridge roadway width, curb-to-curb
						8.2 m = 26.9 ft
Inventory Route, Total Horizontal Clearance	8.5 m = 27.9 ft	Curb or sidewalk width - left	1.5 m = 4.9 ft	Curb or sidewalk width - right	1.5 m = 4.9 ft	
Deck structure type	Concrete Cast-in-Place [1]					
Type of wearing surface	Bituminous [6]					
Deck protection						
Type of membrane/wearing surface						

## Weight Limits

Bypass, detour length	Method to determine inventory rating		Inventory rating	11.3 metric ton = 12.4 tons
0.3 km = 0.2 mi	Method to determine operating rating		Operating rating	12.6 metric ton = 13.9 tons
	Bridge posting	10.0 - 19.9 % below [3]	Design Load	MS 18+Mod / HS 20+Mod [6]

### Functional Details

Average Daily Traffic	19287	Average daily truck traffi		%	Year	1984	Future average daily traffic	19287	Year	1977
Road classification	Other Principal Arterial (Urban) [14]		Lanes on structure	2		Approach roadway width	11 m = 36.1 ft			
Type of service on bridge	Highway-pedestrian [5]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed

Work done by	Work to be done by contract [1]		
Bridge improvement cost	555000	Roadway improvement cost	56000
Length of structure improvement	37.5 m = 123.0 ft	Total project cost	655000
Year of improvement cost estimate			
Border bridge - state		Border bridge - percent responsibility of other state	
Border bridge - structure number			

## Inspection and Sufficiency

Structure status

Posted for load [P]

Appraisal ratings -  
structural

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - superstructure

Very Good [8]

Appraisal ratings -  
roadway alignment

Better than present minimum criteria [7]

Condition ratings - substructure

Serious [3]

Appraisal ratings -  
deck geometry

Basically intolerable requiring high priority of replacement [2]

Condition ratings - deck

Satisfactory [6]

Scour

Channel and channel protection

Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]

Appraisal ratings - water adequacy

Equal to present desirable criteria [8]

Status evaluation

Not applicable [N]

Pier or abutment protection

Sufficiency rating

7

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspected feature meets currently acceptable standards. [1]

Inspection date

May 1990 [0590]

Designated inspection frequency

24

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Not needed [N]

Fracture critical inspection date

Other special inspection

Not needed [N]

Other special inspection date