The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information							
[Illinois [17] Cook County [031]			Chicago [14000]	356 W LAKE ST	41-53-08 = 41.8 087-38-17 = -87.6		
000016602926799 Highway agency district 1		Owner City or Municipa	Highway Agency [04] Maintenance	e responsibility City or Municipal Highway Agency [04]			
Route 1405	LAKI	E ST Toll On free road [3] Features intersected S BR CHICAGO RIV					
Design - Movable - Bas	cule [16]	Design - approach Stee	l [3] ger/Multi-beam or girder [02]	Skew angle 0 Structure F	constructed N/A [0000]		
Total length 101.5 m =			pan 74.7 m = 245.1 ft Curb or sidewalk wi	Deck width, out-to-out 21.3 m = 69.			
Inventory Route, Total Horizontal Clearance 11.5 m = 37.7 f Deck structure type Closed Grating [4] Type of wearing surface Other [9]		Odib of Sidewalk Wi	0.0 III 12.0 II	Oct of Statewark Water Fight			
Deck protection Type of membrane/wearing surface							
Weight Limits Bypass, detour length	Method to deteri	mine inventory rating	Load Factor(LF) [1]	Inventory rating	32.4 metric ton = 35.6 tons		
0.1 km = 0.1 mi Method to determine operating r			, , ,	Operating rating			
Bridge posting Equal to or above legal loads [5]			legal loads [5]	Design Load			

Functional Details								
Average Daily Traffic 14500 Average daily tr	ıck traffi 0 % Year 2002 Future average daily traffic	15600 Year 2021						
Road classification Collector (Urban) [17]	Lanes on structure 4	Approach roadway width 14.6 m = 47.9 ft						
Type of service on bridge Highway-railroad [4]	Direction of traffic 2 - way traffic [2]	Bridge median						
Parallel structure designation No parallel structure exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control	Navigation control on waterway (bridge permit required). [1]						
Navigation vertical clearance 4.8 m = 15.7 ft Navigation horizontal clearance 49.9 m = 163.7 ft								
Minimum navigation vertical clearance, vertical lift brid	ge Minimum vertical cleara	ance over bridge roadway 4.9 m = 16.1 ft						
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]								
Minimum lateral underclearance on right 0 = N/A Minimum lateral underclearance on left 0 = N/A								
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]								
Appraisal ratings - underclearances N/A [N]								
Repair and Replacement Plans								
Type of work to be performed	Work done by Work to be done by contract [1]							
Replacement of bridge or other structure because of substandard load carrying capacity or substantial		provement cost 114000						
bridge roadway geometry. [31]	Length of structure improvement 111.6 m = 366.2 ft	Total project cost 1715000						
	Year of improvement cost estimate							
	Border bridge - state Border	order bridge - percent responsibility of other state						
	Border bridge - structure number							

Inspection and Sufficiency								
Structure status Open, no res	triction [A]	Appraisal ratings - structural	Somewhat better than minimum adequacy to tolerate being left in place as is [5]					
Condition ratings - superstructur	ondition ratings - superstructur		Appraisal ratings - roadway alignment Better than present minimum criteria [7]					
Condition ratings - substructure Fair [5]		Appraisal ratings -	Basically intolerable requiring high priority of replacement [2]					
Condition ratings - deck	Good [7]	deck geometry						
Scour	Bridge foundations	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]						
Channel and channel protection	There are no notice	There are no noticeable or noteworthy deficiencies which affect the condition of the channel. [9]						
Appraisal ratings - water adequac	y Superior to presen	t desirable criteria [9]	Status evaluation	Functionally obsolete [2]				
Pier or abutment protection			Sufficiency rating	64				
Culverts Not applicable. Used	if structure is not a culvert.	[N]						
Traffic safety features - railings	Inj	pected feature meets currently acce	ure meets currently acceptable standards. [1]					
Traffic safety features - transition	No.	ot applicable or a safety feature is no	le or a safety feature is not required. [N]					
Traffic safety features - approach	n guardrail No	ot applicable or a safety feature is no	le or a safety feature is not required. [N]					
Traffic safety features - approach	n guardrail ends No	ot applicable or a safety feature is no	olicable or a safety feature is not required. [N]					
Inspection date September 2007 [0907] Designated inspection frequency 24 Months								
Underwater inspection	Unknown [Y60]	Underwater inspec	June 2009 [06	09]				
•	Not needed [N]	Fracture critical ins						
Other special inspection	Not needed [N]	Other special inspec	ection date					