

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

California [06]	San Francisco County [075]	San Francisco [67000]	04-SF-000-0-SF	37-44-16 = 37.737778	122-25-30 = - 122.425000
34C0016	Highway agency district 4	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	HIGHLAND ST	Toll On free road [3]	Features intersected SAN JOSE AVE		
Design - main Concrete continuous [2]	Design - approach	Kilometerpoint 0 km = 0.0 mi	Year built 1930	Year reconstructed 1973	
3 Tee beam [04]	0 Other [00]	Skew angle 4	Structure Flared		
		Historical significance	Bridge is not eligible for the NRHP. [5]		
Total length 62.8 m = 206.0 ft	Length of maximum span 36.9 m = 121.1 ft	Deck width, out-to-out 13.4 m = 44.0 ft	Bridge roadway width, curb-to-curb 8.5 m = 27.9 ft		
Inventory Route, Total Horizontal Clearance 8.5 m = 27.9 ft	Curb or sidewalk width - left 1.8 m = 5.9 ft	Curb or sidewalk width - right 1.8 m = 5.9 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	30.8 metric ton = 33.9 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	51.7 metric ton = 56.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load		

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Good [7]	Appraisal ratings - deck geometry	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge not over waterway. [N]		
Channel and channel protection	Not applicable. [N]		
Appraisal ratings - water adequacy	N/A [N]	Status evaluation	
Pier or abutment protection		Sufficiency rating	85.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	March 2010 [0310]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	