

HistoricBridges.org - National Bridge Inventory Data Sheet

2010 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Calhoun County [025]	Marengo [51520]	MARENGO TWP SEC 19	42-16-34 = 42.276111	084-55-50 = - 84.930556
13200030000B010	Highway agency district 5	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 1366		MICH AVE	Toll On free road [3]	Features intersected RICE CREEK	
Design - main 1	Concrete [1]	Design - approach 0		Kilometerpoint 25.1 km = 15.6 mi	
	Girder and floorbeam system [03]	Other [00]		Year built 1923	Year reconstructed N/A [0000]
				Skew angle 0	Structure Flared
				Historical significance Bridge is not eligible for the NRHP. [5]	
Total length	15.2 m = 49.9 ft	Length of maximum span	15.2 m = 49.9 ft	Deck width, out-to-out	9.3 m = 30.5 ft
				Bridge roadway width, curb-to-curb	7.3 m = 24.0 ft
Inventory Route, Total Horizontal Clearance	7.4 m = 24.3 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 1.6 km = 1.0 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	21.2 metric ton = 23.3 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	35.5 metric ton = 39.1 tons
Bridge posting	30.0 - 39.9 % below [1]		Design Load	

Functional Details

Average Daily Traffic	<input type="text" value="1155"/>	Average daily truck traffi	<input type="text" value="14"/>	%	Year	<input type="text" value="1995"/>	Future average daily traffic	<input type="text" value="2067"/>	Year	<input type="text" value="2023"/>
Road classification	<input type="text" value="Major Collector (Rural) [07]"/>		Lanes on structure	<input type="text" value="2"/>		Approach roadway width	<input type="text" value="11.6 m = 38.1 ft"/>			
Type of service on bridge	<input type="text" value="Highway [1]"/>		Direction of traffic	<input type="text" value="2 - way traffic [2]"/>		Bridge median	<input type="text"/>			
Parallel structure designation	<input type="text" value="No parallel structure exists. [N]"/>									
Type of service under bridge	<input type="text" value="Waterway [5]"/>		Lanes under structure	<input type="text" value="0"/>		Navigation control	<input type="text"/>			
Navigation vertical clearanc	<input type="text" value="0 = N/A"/>		Navigation horizontal clearance	<input type="text" value="0 = N/A"/>						
Minimum navigation vertical clearance, vertical lift bridge	<input type="text"/>					Minimum vertical clearance over bridge roadway	<input type="text" value="99.99 m = 328.1 ft"/>			
Minimum lateral underclearance reference feature	<input type="text" value="Feature not a highway or railroad [N]"/>									
Minimum lateral underclearance on right	<input type="text" value="0 = N/A"/>					Minimum lateral underclearance on left	<input type="text" value="0 = N/A"/>			
Minimum Vertical Underclearance	<input type="text" value="0 = N/A"/>		Minimum vertical underclearance reference feature	<input type="text" value="Feature not a highway or railroad [N]"/>						
Appraisal ratings - underclearances	<input type="text" value="N/A [N]"/>									

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost

Roadway improvement cost

Length of structure improvement

Total project cost

Year of improvement cost estimate

Border bridge - state

Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Posted for load [P]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - superstructure	<input type="text" value="Serious [3]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - deck	<input type="text" value="Poor [4]"/>		
Scour	<input [u]"="" been="" evaluated="" for="" foundation="" has="" not="" scour.="" that="" type="text" unknown\"="" value="Bridge with \"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="15.4"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="September 2009 [0909]"/>	Designated inspection frequency	<input type="text" value="12"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>