

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Florida [12]	Pinellas County [103]	Tarpon Springs [71150]	0.4 MI W/O GRAND BLVD	28-08-59.96 = 28.149989	082-45-54.73 = -82.765203
154000	Highway agency district: 7	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	N SPRING BLVD	Toll On free road [3]	Features intersected	MINETTA BRANCH	
Design - main Steel [3]	Design - approach Prestressed concrete [5]	Kilometerpoint 123.3 km = 76.4 mi	Year built 1924	Year reconstructed N/A [0000]	
1	Movable - Bascule [16]	9	Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared
		Historical significance	Bridge is possibly eligible for the NRHP. [3]		
Total length 109.2 m = 358.3 ft	Length of maximum span 12.8 m = 42.0 ft	Deck width, out-to-out 8.5 m = 27.9 ft	Bridge roadway width, curb-to-curb 6.2 m = 20.3 ft		
Inventory Route, Total Horizontal Clearance 6.2 m = 20.3 ft	Curb or sidewalk width - left 0.7 m = 2.3 ft	Curb or sidewalk width - right 0.7 m = 2.3 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface					
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	15.9 metric ton = 17.5 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	22 metric ton = 24.2 tons
	Bridge posting		Design Load	

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Good [7]		
Scour	Bridge is scour critical; bridge foundations determined to be unstable. [3]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection	In place but re-evaluation of design suggested [4]	Sufficiency rating	48.3
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	July 2018 [0718]	Designated inspection frequency	24 Months
Underwater inspection	Every two years [Y24]	Underwater inspection date	June 2018 [0618]
Fracture critical inspection	Every year [Y12]	Fracture critical inspection date	July 2018 [0718]
Other special inspection	Every year [Y12]	Other special inspection date	July 2018 [0718]