

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Illinois [17]	Winnebago County [201]	Unknown [00000]	1 MI SE OF ROCKTON	42-26-22 = 42.4	089-02-33 = -89.0
101993000409	Highway agency district 2	Owner Local Park, Forest, or Reservation Agen	Maintenance responsibility	Local Park, Forest, or Reservation Agency	
Route 5104	HONONEGAH PRES RD	Toll On free road [3]	Features intersected DRY RUN CREEK		
Design - main Concrete [1]	Design - approach	Kilometerpoint 33.8 km = 21.0 mi	Year built 1925	Year reconstructed #Num!	
1	Arch - Thru [12]	0	Other [00]	Skew angle 0	Structure Flared
		Historical significance Bridge is eligible for the NRHP. [2]			
Total length 24.4 m = 80.1 ft	Length of maximum span 22.9 m = 75.1 ft	Deck width, out-to-out 6.6 m = 21.7 ft	Bridge roadway width, curb-to-curb 5.8 m = 19.0 ft		
Inventory Route, Total Horizontal Clearance 5.7 m = 18.7 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0 km = 0.0 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	24.3 metric ton = 26.7 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	33.3 metric ton = 36.6 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	M 13.5 / H 15 [2]	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - substructure	<input type="text" value="Good [7]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - deck	<input type="text" value="Satisfactory [6]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for assessed or calculated scour condition. [5]"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present minimum criteria [6]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="57.5"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Inspection date	<input type="text" value="April 2010 [0410]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>