

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Illinois [17]	Iroquois County [075]	Artesia [02401]	1.5MI N 1.5W CISSNA	40-35-42 = 40.595000	087-54-18 = - 87.905000
38303809202	Highway agency district 3	Owner Town or Township Highway Agency [03]	Maintenance responsibility	Town or Township Highway Agency [03]	
Route 323	TR 323	Toll On free road [3]	Features intersected	TR OF LITTLE MUD CR	
Design - main 1	Steel [3]	Design - approach 0	Other [00]	Kilometerpoint	
	Truss - Thru [10]			Year built 1908	Year reconstructed N/A [0000]
				Skew angle 0	Structure Flared
				Historical significance Historical significance is not determinable at this time. [4]	
Total length 12.8 m = 42.0 ft	Length of maximum span 12.2 m = 40.0 ft	Deck width, out-to-out 4.9 m = 16.1 ft	Bridge roadway width, curb-to-curb 4.8 m = 15.7 ft		
Inventory Route, Total Horizontal Clearance 4.8 m = 15.7 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating		Inventory rating 3.6 metric ton = 4.0 tons
	Method to determine operating rating		Operating rating 4.5 metric ton = 5.0 tons
Bridge posting		Design Load	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Posted for load [P]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - superstructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Serious [3]"/>	Appraisal ratings - deck geometry	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Scour calculation/evaluation has not been made. [6]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="26.7"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="June 1990 [0690]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Every two years [Y24]"/>	Fracture critical inspection date	<input type="text" value="June 1990 [0690]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Illinois [17]	Iroquois County [075]	Artesia [02401]	1.5MI N 1.5W CISSNA	40-35-37 = 40.5	087-55-42 = -87.9
38305933831	Highway agency district 3	Owner Town or Township Highway Agency [03]	Maintenance responsibility	Town or Township Highway Agency [03]	
Route 323	TR 323	Toll On free road [3]	Features intersected	TR OF LITTLE MUD CR	
Design - main 1	Prestressed concrete [5] Box beam or girders - Multiple [05]	Design - approach 0	Other [00]	Kilometerpoint 91.7 km = 56.9 mi	Year built 2007
				Year reconstructed #Num!	Skew angle 0
				Structure Flared	Historical significance Bridge is not eligible for the NRHP. [5]
Total length 24.3 m = 79.7 ft	Length of maximum span 23.4 m = 76.8 ft	Deck width, out-to-out 9.1 m = 29.9 ft	Bridge roadway width, curb-to-curb 9.1 m = 29.9 ft		
Inventory Route, Total Horizontal Clearance 9.1 m = 29.9 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Precast Panels [2]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.1 km = 0.1 mi	Method to determine inventory rating Allowable Stress(AS) [2]	Inventory rating 32.4 metric ton = 35.6 tons
	Method to determine operating rating Allowable Stress(AS) [2]	Operating rating 44.1 metric ton = 48.5 tons
Bridge posting Equal to or above legal loads [5]	Design Load MS 18 / HS 20 [5]	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present desirable criteria [8]
Condition ratings - superstructure	Excellent [9]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Excellent [9]	Appraisal ratings - deck geometry	Better than present minimum criteria [7]
Condition ratings - deck	Excellent [9]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	
Pier or abutment protection		Sufficiency rating	100
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	July 2010 [0710]	Designated inspection frequency	48 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	