

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Illinois [17]	Cook County [031]	Chicago [14000]	375 W & 300 S	41-52-41 = 41.8	087-38-17 = -87.6
000016602627329	Highway agency district 1	Owner City or Municipal Highway Agency [04]	Maintenance responsibility	City or Municipal Highway Agency [04]	
Route 1422	JACKSON BLVD	Toll On free road [3]	Features intersected S BR CHICAGO RIV		
Design - main Steel [3]	Design - approach Steel [3]	Kilometerpoint 1140.8 km = 707.3 mi	Year built 1916	Year reconstructed N/A [0000]	
1	Movable - Bascule [16]	3	Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared
		Historical significance Bridge is eligible for the NRHP. [2]			
Total length 83.2 m = 273.0 ft	Length of maximum span 61.6 m = 202.1 ft	Deck width, out-to-out 19.5 m = 64.0 ft	Bridge roadway width, curb-to-curb 11.3 m = 37.1 ft		
Inventory Route, Total Horizontal Clearance 11.2 m = 36.7 ft	Curb or sidewalk width - left 2.7 m = 8.9 ft	Curb or sidewalk width - right 2.7 m = 8.9 ft			
Deck structure type	Open Grating [3]				
Type of wearing surface	Other [9]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0 km = 0.0 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	32.4 metric ton = 35.6 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	44.1 metric ton = 48.5 tons
Bridge posting	Equal to or above legal loads [5]	Design Load		

Functional Details

Average Daily Traffic	8900	Average daily truck traffi	14	%	Year	2006	Future average daily traffic	7920	Year	2021
Road classification	Collector (Urban) [17]	Lanes on structure	4		Approach roadway width	11.3 m = 37.1 ft				
Type of service on bridge	Highway [1]	Direction of traffic	1 - way traffic [1]		Bridge median					
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0		Navigation control	Navigation control on waterway (bridge permit required). [1]				
Navigation vertical clearanc	4.8 m = 15.7 ft		Navigation horizontal clearance	44.8 m = 147.0 ft						
Minimum navigation vertical clearance, vertical lift bridge		Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft							
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	2056000	Roadway improvement cost	206000						
	Length of structure improvement	116.7 m = 382.9 ft		Total project cost	3084000					
	Year of improvement cost estimate									
	Border bridge - state		Border bridge - percent responsibility of other state							
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Good [7]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Superior to present desirable criteria [9]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="65"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Inspection date	<input type="text" value="September 2008 [0908]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Unknown [Y60]"/>	Underwater inspection date	<input type="text" value="November 2007 [1107]"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>