

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Illinois [17]	Kane County [089]	Aurora [03012]	STOLP ISLAND	41-45-33 = 41.7	088-18-53 = -88.3
000045001210309	Highway agency district 1	Owner City or Municipal Highway Agency [04]	Maintenance responsibility City or Municipal Highway Agency [04]		
Route 1522	NEW YORK STREET	Toll On free road [3]	Features intersected FOX RIVER		
Design - main Concrete [1]	Design - approach	Kilometerpoint 43.4 km = 26.9 mi	Year built 1931	Year reconstructed 1992	
11	Other [00]	0	Other [00]	Skew angle 0	Structure Flared
				Historical significance	Bridge is possibly eligible for the NRHP. [3]
Total length 204.2 m = 670.0 ft	Length of maximum span 20.6 m = 67.6 ft	Deck width, out-to-out 20.4 m = 66.9 ft	Bridge roadway width, curb-to-curb 14 m = 45.9 ft		
Inventory Route, Total Horizontal Clearance 14 m = 45.9 ft	Curb or sidewalk width - left 2.7 m = 8.9 ft	Curb or sidewalk width - right 2.7 m = 8.9 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection	Epoxy Coated Reinforcing [1]				
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	32.4 metric ton = 35.6 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	44.1 metric ton = 48.5 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18 / HS 20 [5]	

Functional Details

Average Daily Traffic	13300	Average daily truck traffi	3	%	Year	2006	Future average daily traffic	26055	Year	2020
Road classification	Minor Arterial (Urban) [16]		Lanes on structure	4		Approach roadway width	14 m = 45.9 ft			
Type of service on bridge	Highway [1]		Direction of traffic	1 - way traffic [1]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	4740000	Roadway improvement cost	474000						
	Length of structure improvement	214.6 m = 704.1 ft		Total project cost	7110000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - superstructure	<input type="text" value="Good [7]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Good [7]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Good [7]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Superior to present desirable criteria [9]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="78.6"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="May 2008 [0508]"/>	Designated inspection frequency	<input type="text" value="48"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>