

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Illinois [17]	Cook County [031]	Chicago [14000]	400 S & 361 W	41-52-36 = 41.8	087-38-14 = -87.6
000016605126836	Highway agency district 1	Owner City or Municipal Highway Agency [04]	Maintenance responsibility	City or Municipal Highway Agency [04]	
Route 1423	VAN BUREN ST	Toll On free road [3]	Features intersected S BR CHICAGO RIVER		
Design - main Steel [3]	Design - approach Steel [3]	Kilometerpoint 122.3 km = 75.8 mi	Year built 1956	Year reconstructed N/A [0000]	
1 Movable - Bascule [16]	2 Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared		
		Historical significance Bridge is not eligible for the NRHP. [5]			
Total length 81.4 m = 267.1 ft	Length of maximum span 64.1 m = 210.3 ft	Deck width, out-to-out 21 m = 68.9 ft	Bridge roadway width, curb-to-curb 13.4 m = 44.0 ft		
Inventory Route, Total Horizontal Clearance 13.4 m = 44.0 ft	Curb or sidewalk width - left 2.5 m = 8.2 ft	Curb or sidewalk width - right 2.5 m = 8.2 ft			
Deck structure type	Open Grating [3]				
Type of wearing surface	Other [9]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0 km = 0.0 mi	Method to determine inventory rating Allowable Stress(AS) [2]	Inventory rating 25.2 metric ton = 27.7 tons
	Method to determine operating rating Allowable Stress(AS) [2]	Operating rating 41.4 metric ton = 45.5 tons
Bridge posting Equal to or above legal loads [5]	Design Load	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - superstructure	Serious [3]	Appraisal ratings - roadway alignment	Better than present minimum criteria [7]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Superior to present desirable criteria [9]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	30.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions	Not applicable or a safety feature is not required. [N]		
Traffic safety features - approach guardrail	Not applicable or a safety feature is not required. [N]		
Traffic safety features - approach guardrail ends	Not applicable or a safety feature is not required. [N]		
Inspection date	September 2008 [0908]	Designated inspection frequency	24 Months
Underwater inspection	Unknown [Y60]	Underwater inspection date	July 2009 [0709]
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	