

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Indiana [18]	Marion County [097]	Indianapolis [36000]	00.30 S OF 30TH ST	39-48-19.87 = 39.805519	086-09-10.72 = -86.152978
4900144	Highway agency district: 3	Owner City or Municipal Highway Agency [04]	Maintenance responsibility City or Municipal Highway Agency [04]		
Route 0	DELAWARE ST	Toll On free road [3]	Features intersected FALL CREEK		
Design - main Concrete [1]	Design - approach	Kilometerpoint 0 km = 0.0 mi	Year built 1924	Year reconstructed N/A [0000]	
3 Arch - Deck [11]	0 Other [00]	Skew angle 17	Structure Flared		
		Historical significance	Bridge is eligible for the NRHP. [2]		
Total length 79.2 m = 259.9 ft	Length of maximum span 27.3 m = 89.6 ft	Deck width, out-to-out 25.6 m = 84.0 ft	Bridge roadway width, curb-to-curb 18.2 m = 59.7 ft		
Inventory Route, Total Horizontal Clearance 18.2 m = 59.7 ft	Curb or sidewalk width - left 3 m = 9.8 ft	Curb or sidewalk width - right 3 m = 9.8 ft			
Deck structure type	Not applicable [N]				
Type of wearing surface	Bituminous [6]				
Deck protection	Not applicable (applies only to structures with no deck) [N]				
Type of membrane/wearing surface	Not applicable (applies only to structures with no deck) [N]				

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	Inventory rating 32.7 metric ton = 36.0 tons
	Method to determine operating rating	Operating rating 40.8 metric ton = 44.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Not Applicable [N]		

Scour

Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]

Channel and channel protection

Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]

Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	Functionally obsolete [2]
------------------------------------	---	-------------------	---------------------------

Pier or abutment protection		Sufficiency rating	77.1
-----------------------------	--	--------------------	------

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings	
Traffic safety features - transitions	
Traffic safety features - approach guardrail	
Traffic safety features - approach guardrail ends	

Inspection date	August 2018 [0818]	Designated inspection frequency	24	Months
Underwater inspection	Not needed [N]	Underwater inspection date		
Fracture critical inspection	Not needed [N]	Fracture critical inspection date		
Other special inspection	Not needed [N]	Other special inspection date		