

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Indiana [18]	Orange County [117]	Unknown [00000]	00.03 W of CR 325 E	38-25-22.33 = 38.422869	086-23-38.77 = -86.394103
5900068	Highway agency district: 6	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 104	CR 910S	Toll On free road [3]	Features intersected	Branch of Patoka River	
Design - main 1	Steel [3] Stringer/Multi-beam or girder [02]	Design - approach 0	Other [00]	Kilometerpoint 0 km = 0.0 mi	Year built 1940 Year reconstructed 1993
				Skew angle 0	Structure Flared
				Historical significance Bridge is not eligible for the NRHP. [5]	
Total length	9.2 m = 30.2 ft	Length of maximum span	8.6 m = 28.2 ft	Deck width, out-to-out	4.9 m = 16.1 ft
Inventory Route, Total Horizontal Clearance	4.9 m = 16.1 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Open Grating [3]				
Type of wearing surface	Other [9]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	32.7 metric ton = 36.0 tons
19.9 km = 12.3 mi	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	54.4 metric ton = 59.8 tons
Bridge posting	Equal to or above legal loads [5]		Design Load	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Good [7]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Equal to present desirable criteria [8]
Condition ratings - deck	Good [7]		

Scour

Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]

Channel and channel protection

Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]

Appraisal ratings - water adequacy	Somewhat better than minimum adequacy to tolerate being left in place as is [5]	Status evaluation	
------------------------------------	---	-------------------	--

Pier or abutment protection		Sufficiency rating	82
-----------------------------	--	--------------------	----

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings	
Traffic safety features - transitions	
Traffic safety features - approach guardrail	
Traffic safety features - approach guardrail ends	

Inspection date	May 2018 [0518]	Designated inspection frequency	24	Months
Underwater inspection	Not needed [N]	Underwater inspection date		
Fracture critical inspection	Not needed [N]	Fracture critical inspection date		
Other special inspection	Not needed [N]	Other special inspection date		