

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Indiana [18]	Vigo County [167]	West Terre Haute [83384]	00.90 W THORPE RD	39-26-44.77 = 39.445769	087-29-51.62 = -87.497672
8400172	Highway agency district: 1	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	Old NATIONAL Rd	Toll On free road [3]	Features intersected	CLEAR CREEK	
Design - main Concrete [1]	Design - approach Other [00]	Kilometerpoint 0 km = 0.0 mi	Year built 1919	Year reconstructed N/A [0000]	
2	Arch - Deck [11]	Skew angle 0	Structure Flared	Historical significance Bridge is eligible for the NRHP. [2]	
Total length 28.1 m = 92.2 ft	Length of maximum span 12.8 m = 42.0 ft	Deck width, out-to-out 7 m = 23.0 ft	Bridge roadway width, curb-to-curb 6.2 m = 20.3 ft		
Inventory Route, Total Horizontal Clearance 6.2 m = 20.3 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.5 km = 0.3 mi	Method to determine inventory rating		Inventory rating 29 metric ton = 31.9 tons
	Method to determine operating rating		Operating rating 39.9 metric ton = 43.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	

Functional Details

Average Daily Traffic	322	Average daily truck traffi	2	%	Year	2017	Future average daily traffic	440	Year	2037
Road classification	Local (Urban) [19]		Lanes on structure	2		Approach roadway width	4.9 m = 16.1 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	634000	Roadway improvement cost	190000						
	Length of structure improvement	35.1 m = 115.2 ft		Total project cost	1112000					
	Year of improvement cost estimate	2015								
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Bridge is scour critical; bridge foundations determined to be unstable. [3]"/>		
Channel and channel protection	<input type="text" value="Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present minimum criteria [6]"/>	Status evaluation	<input type="text"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="66.8"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="July 2017 [0717]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>