

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Iowa [19] Winneshiek County [191] Unknown [00000] 1000932 43-26-00 = 43.433333 091-56-50 = - 91.947222

349700 Highway agency district 2 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 LOCAL Toll On free road [3] Features intersected COLD WATER CREEK

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built 1962 Year reconstructed N/A [0000]

Skew angle 0 Structure Flared

Historical significance Bridge is not eligible for the NRHP. [5]

Total length 15.2 m = 49.9 ft Length of maximum span 15.2 m = 49.9 ft Deck width, out-to-out 6.4 m = 21.0 ft Bridge roadway width, curb-to-curb 6.4 m = 21.0 ft

Inventory Route, Total Horizontal Clearance 6.1 m = 20.0 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Concrete Cast-in-Place [1]

Type of wearing surface Monolithic Concrete (concurrently placed with structural deck) [1]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.8 km = 0.5 mi Method to determine inventory rating No rating analysis performed [5] Inventory rating 13.5 metric ton = 14.9 tons

Method to determine operating rating No rating analysis performed [5] Operating rating 19.8 metric ton = 21.8 tons

Bridge posting Equal to or above legal loads [5] Design Load

Functional Details

Average Daily Traffic	70	Average daily truck traffi	0	%	Year	2001	Future average daily traffic	76	Year	2029
Road classification	Local (Rural) [09]		Lanes on structure	2		Approach roadway width	7.3 m = 24.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft				Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft				
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Bridge rehabilitation because of general structure deterioration or inadequate strength. [35]	Bridge improvement cost	124000	Roadway improvement cost	28000						
	Length of structure improvement	26.5 m = 86.9 ft		Total project cost	152000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input [u]"="" been="" evaluated="" for="" foundation="" has="" not="" scour.="" that="" type="text" unknown\"="" value="Bridge with \"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present minimum criteria [6]"/>	Status evaluation	<input type="text"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="46.2"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="March 2009 [0309]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Unknown [N00]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Every two years [Y24]"/>	Fracture critical inspection date	<input type="text" value="March 2009 [0309]"/>
Other special inspection	<input type="text" value="Unknown [N00]"/>	Other special inspection date	<input type="text"/>