

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Iowa [19]	Winneshiek County [191]	Unknown [00000]	990906	43-24-50 = 43.413889	091-57-30 = - 91.958333
348800	Highway agency district 2	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	LOCAL ROAD	Toll On free road [3]	Features intersected	UPPER IOWA RIVER	
Design - main Steel [3]	Design - approach Steel [3]	Kilometerpoint 0 km = 0.0 mi	Year built #Num!	Year reconstructed N/A [0000]	
1	Truss - Thru [10]	1	Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared
		Historical significance Bridge is eligible for the NRHP. [2]			
Total length 46 m = 150.9 ft	Length of maximum span 39.3 m = 128.9 ft	Deck width, out-to-out 4.9 m = 16.1 ft	Bridge roadway width, curb-to-curb 4.9 m = 16.1 ft		
Inventory Route, Total Horizontal Clearance 4.6 m = 15.1 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Wood or Timber [8]				
Type of wearing surface					
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 1 km = 0.6 mi	Method to determine inventory rating	No rating analysis performed [5]	Inventory rating	4.5 metric ton = 5.0 tons
	Method to determine operating rating	No rating analysis performed [5]	Operating rating	6.3 metric ton = 6.9 tons
Bridge posting			Design Load	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status

Posted for load [P]

Appraisal ratings -
structural

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - superstructure

Serious [3]

Appraisal ratings -
roadway alignment

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - substructure

Satisfactory [6]

Appraisal ratings -
deck geometry

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - deck

Fair [5]

Scour

Bridge with "unknown" foundation that has not been evaluated for scour. [U]

Channel and channel protection

Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]

Appraisal ratings - water adequacy

Meets minimum tolerable limits to be left in place as is [4]

Status evaluation

Structurally deficient [1]

Pier or abutment protection

Sufficiency rating

16.7

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

March 2009 [0309]

Designated inspection frequency

12

Months

Underwater inspection

Unknown [N00]

Underwater inspection date

Fracture critical inspection

Every year [Y12]

Fracture critical inspection date

March 2009 [0309]

Other special inspection

Unknown [N00]

Other special inspection date