

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Kansas [20]	Lyon County [111]	Unknown [00000]	7.0W 0.5S NEOSHO RAPIDS	38-21-56.90 = 38.365806	096-06-53.60 = -96.114889
000560951005247	Highway agency district: 1	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 5625	RD P (N.0-25.7)	Toll On free road [3]	Features intersected	COTTONWOOD RIVER	
Design - main 1	Steel [3] Truss - Thru [10]	Design - approach 0	Other [00]	Kilometerpoint 0 km = 0.0 mi	Year built 1910 Year reconstructed N/A [0000]
				Skew angle 0	Structure Flared
				Historical significance	Bridge is possibly eligible for the NRHP. [3]
Total length	66.8 m = 219.2 ft	Length of maximum span	65.5 m = 214.9 ft	Deck width, out-to-out	4.9 m = 16.1 ft
Bridge roadway width, curb-to-curb	4.8 m = 15.7 ft	Inventory Route, Total Horizontal Clearance	4.8 m = 15.7 ft	Curb or sidewalk width - left	0 m = 0.0 ft
				Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	7 metric ton = 7.7 tons
0.6 km = 0.4 mi	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	11 metric ton = 12.1 tons
Bridge posting			Design Load	MS 18 / HS 20 [5]

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - superstructure	Fair [5]	Appraisal ratings - roadway alignment	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Equal to present minimum criteria [6]
Condition ratings - deck	Fair [5]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present minimum criteria [6]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection		Sufficiency rating	32.6
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	October 2013 [1013]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	October 2013 [1013]
Other special inspection	Not needed [N]	Other special inspection date	