

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Kentucky [21]	Franklin County [073]	Unknown [00735]	ST CLAIR-200FT N OF 2ND S	38-11-47 = 38.196389	084-52-43 = - 84.878611
037B00065N	Highway agency district 5	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 60	US-60X	Toll On free road [3]	Features intersected KENTUCKY RIVER		
Design - main Steel [3]	Design - approach	Kilometerpoint 6 km = 3.7 mi	Year built 1893	Year reconstructed 1956	
1 Truss - Thru [10]	0 Other [00]	Skew angle 0	Structure Flared		
		Historical significance	Bridge is on the NRHP. [1]		
Total length 124.7 m = 409.1 ft	Length of maximum span 123.7 m = 405.9 ft	Deck width, out-to-out 7.3 m = 24.0 ft	Bridge roadway width, curb-to-curb 7.3 m = 24.0 ft		
Inventory Route, Total Horizontal Clearance 7.3 m = 24.0 ft	Curb or sidewalk width - left 1.8 m = 5.9 ft	Curb or sidewalk width - right 1.8 m = 5.9 ft			
Deck structure type	Open Grating [3]				
Type of wearing surface	Other [9]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	8.2 metric ton = 9.0 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	8.2 metric ton = 9.0 tons
Bridge posting		Design Load		

Functional Details

Average Daily Traffic	6070	Average daily truck traffi	0	%	Year	2011	Future average daily traffic	7405	Year	2031
Road classification	Collector (Urban) [17]	Lanes on structure	2	Approach roadway width	8.5 m = 27.9 ft					
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]		Bridge median					
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control						
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	6.1 m = 20.0 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A			Minimum lateral underclearance on left	0 = N/A					
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	1534000	Roadway improvement cost	400000						
	Length of structure improvement	12.4 m = 40.7 ft		Total project cost	1933000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Posted for load [P]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - superstructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Superior to present desirable criteria [9]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="12.9"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="August 2011 [0811]"/>	Designated inspection frequency	<input type="text" value="12"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Every two years [Y24]"/>	Fracture critical inspection date	<input type="text" value="September 2008 [0908]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>