

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Maine [23]	Androscoggin County [001]	Lisbon [40035]	200 FT NE'LY RTE 196	44-01-56 = 44.032222	070-06-13 = - 70.103611
0063	Highway agency district 1	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 0	VILLAGE ST. (WEBST	Toll On free road [3]	Features intersected	SABBATUS RIVER	
Design - main Concrete [1]	Design - approach	Kilometerpoint 9.7 km = 6.0 mi	Year built 1913	Year reconstructed 1987	
2 Arch - Deck [11]	0 Other [00]	Skew angle 15	Structure Flared		
		Historical significance	Bridge is not eligible for the NRHP. [5]		
Total length 42.7 m = 140.1 ft	Length of maximum span 20.4 m = 66.9 ft	Deck width, out-to-out 11.4 m = 37.4 ft	Bridge roadway width, curb-to-curb 8.6 m = 28.2 ft		
Inventory Route, Total Horizontal Clearance 8.5 m = 27.9 ft	Curb or sidewalk width - left 0.1 m = 0.3 ft	Curb or sidewalk width - right 1.8 m = 5.9 ft			
Deck structure type	Other [9]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	24.5 metric ton = 27.0 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	24.5 metric ton = 27.0 tons
Bridge posting	Equal to or above legal loads [5]	Design Load		

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - superstructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - deck	<input type="text" value="Satisfactory [6]"/>		
Scour	<input type="text" value="Bridge is scour critical; bridge foundations determined to be unstable. [3]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Superior to present desirable criteria [9]"/>	Status evaluation	<input type="text"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="75.2"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="August 2010 [0810]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>