

# HistoricBridges.org - National Bridge Inventory Data Sheet

2011 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

## Basic Information

Maryland [24]	Frederick County [021]	Unknown [00000]	1.5 MI W OLD MIDDLETOWN R	00-00-00 = 0.000000	000-00-00 = - 0.000000
200000F-2204010	Highway agency district 7	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 218		SUMANTOWN ROAD	Toll On free road [3]	Features intersected CATOCTIN CREEK	
Design - main	Steel [3]	Design - approach		Kilometerpoint	228.5 km = 141.7 mi
1	Truss - Thru [10]	0	Other [00]	Year built	1910
				Year reconstructed	1999
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is not eligible for the NRHP. [5]
Total length	30.8 m = 101.1 ft	Length of maximum span	30.8 m = 101.1 ft	Deck width, out-to-out	4.7 m = 15.4 ft
Inventory Route, Total Horizontal Clearance	4.5 m = 14.8 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Wood or Timber [8]				
Type of wearing surface					
Deck protection					
Type of membrane/wearing surface					

## Weight Limits

Bypass, detour length	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	14.4 metric ton = 15.8 tons
0.6 km = 0.4 mi	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	24.3 metric ton = 26.7 tons
	Bridge posting		Design Load	

### Functional Details

Average Daily Traffic	99	Average daily truck traffi	5	%	Year	1996	Future average daily traffic	182	Year	2011
Road classification	Minor Collector (Rural) [08]		Lanes on structure	1		Approach roadway width	3.4 m = 11.2 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	3.96 m = 13.0 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost

Roadway improvement cost

Length of structure improvement

Total project cost

Year of improvement cost estimate

Border bridge - state

Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Good [7]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Good [7]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - deck	Good [7]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Better than present minimum criteria [7]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection		Sufficiency rating	46.6
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	October 2010 [1010]	Designated inspection frequency	12 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every year [Y12]	Fracture critical inspection date	October 2010 [1010]
Other special inspection	Not needed [N]	Other special inspection date	