

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Michigan [26]	Ionia County [067]	Odessa [60200]	0.25 MI E OF LAKE ODESSA	42-46-39 = 42.777500	085-07-24 = - 85.123333
34310H00005B010	Highway agency district 3	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	HUDDLE ROAD	Toll On free road [3]	Features intersected	TUPPER CREEK	
Design - main Concrete [1]	Design - approach	Kilometerpoint 18.3 km = 11.3 mi	Year built 1923	Year reconstructed N/A [0000]	
1	Girder and floorbeam system [03]	0 Other [00]	Skew angle 0	Structure Flared	
			Historical significance	Bridge is not eligible for the NRHP. [5]	
Total length 10.6 m = 34.8 ft	Length of maximum span 10 m = 32.8 ft	Deck width, out-to-out 8.2 m = 26.9 ft	Bridge roadway width, curb-to-curb	6.7 m = 22.0 ft	
Inventory Route, Total Horizontal Clearance 6.7 m = 22.0 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft		
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	32.7 metric ton = 36.0 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	43.5 metric ton = 47.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18+Mod / HS 20+Mod [6]	

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - deck	<input type="text" value="Poor [4]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for assessed or calculated scour condition. [5]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Better than present minimum criteria [7]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="68"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="November 2008 [1108]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>