

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Gratiot County [057]	Seville [72580]	SEC. 31 SEVILLE TWP.	00-00-00 = 0.000000	000-00-00 = - 0.000000
29200019000B010	Highway agency district 4	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 2974	LINCOLN ROAD	Toll On free road [3]	Features intersected	PINE RIVER	
Design - main Concrete [1]	Design - approach	Kilometerpoint 0 km = 0.0 mi	Year built 1925	Year reconstructed N/A [0000]	
1	Girder and floorbeam system [03]	0	Other [00]	Skew angle 45	Structure Flared
		Historical significance		Bridge is on the NRHP. [1]	
Total length 27.7 m = 90.9 ft	Length of maximum span 26.8 m = 87.9 ft	Deck width, out-to-out 7.9 m = 25.9 ft	Bridge roadway width, curb-to-curb	6.1 m = 20.0 ft	
Inventory Route, Total Horizontal Clearance 6 m = 19.7 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft		
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 1 km = 0.6 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	14.5 metric ton = 16.0 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	32.7 metric ton = 36.0 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18+Mod / HS 20+Mod [6]	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - superstructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - substructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Poor [4]"/>		
Scour	<input type="text" value="Bridge is scour critical; bridge foundations determined to be unstable. [3]"/>		
Channel and channel protection	<input type="text" value="Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="17.6"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="May 1999 [0599]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Unknown [N24]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Unknown [N24]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Unknown [N24]"/>	Other special inspection date	<input type="text"/>