

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Wexford County [165]	South Branch [74820]	2 MI N OF LAKE CO LINE	44-12-15 = 44.204167	085-48-03 = - 85.800833
83183011000B010	Highway agency district 2	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 37	M-37	Toll On free road [3]	Features intersected	PINE RIVER	
Design - main Steel [3]	Design - approach	Kilometerpoint 444.2 km = 275.4 mi	Year built 1948	Year reconstructed N/A [0000]	
3	Girder and floorbeam system [03]	0	Other [00]	Skew angle 0	Structure Flared
			Historical significance	Bridge is not eligible for the NRHP. [5]	
Total length 99 m = 324.8 ft	Length of maximum span 37.2 m = 122.1 ft	Deck width, out-to-out 13 m = 42.7 ft	Bridge roadway width, curb-to-curb	10.7 m = 35.1 ft	
Inventory Route, Total Horizontal Clearance 12.5 m = 41.0 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft		
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Latex Concrete or similar additive [3]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	37.3 metric ton = 41.0 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	99.9 metric ton = 109.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18 / HS 20 [5]	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Better than present minimum criteria [7]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Equal to present minimum criteria [6]
Condition ratings - deck	Poor [4]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	91.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	May 2008 [0508]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Unknown [Y15]	Fracture critical inspection date	June 2009 [0609]
Other special inspection	Not needed [N]	Other special inspection date	