

HistoricBridges.org - National Bridge Inventory Data Sheet

2012 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Alger County [003]	Mathias [52360]	W LTS OF TRENARY	46-11-42 = 46.195000	086-58-20 = - 86.972222
40	Highway agency district 1	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 67	M-67	Toll On free road [3]	Features intersected	SCOTTS CREEK	
Design - main 1	Concrete [1] Arch - Deck [11]	Design - approach 0	Other [00]	Kilometerpoint 147.1 km = 91.2 mi	Year built 1914
				Year reconstructed 1953	Skew angle 0
				Structure Flared	Historical significance Bridge is not eligible for the NRHP. [5]
Total length 13.7 m = 44.9 ft	Length of maximum span 13.7 m = 44.9 ft	Deck width, out-to-out 13.2 m = 43.3 ft	Bridge roadway width, curb-to-curb 11.6 m = 38.1 ft	Inventory Route, Total Horizontal Clearance 12.5 m = 41.0 ft	Curb or sidewalk width - left 0.4 m = 1.3 ft
				Curb or sidewalk width - right 0.4 m = 1.3 ft	
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 3.1 km = 1.9 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating 40.5 metric ton = 44.6 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating 66.9 metric ton = 73.6 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	M 18 / H 20 [4]

Functional Details

Average Daily Traffic	1352	Average daily truck traffi	9	%	Year	2007	Future average daily traffic	1509	Year	2018
Road classification	Minor Arterial (Rural) [06]		Lanes on structure	2		Approach roadway width	12.2 m = 40.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost

Roadway improvement cost

Length of structure improvement

Total project cost

Year of improvement cost estimate

Border bridge - state

Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - superstructure	Fair [5]	Appraisal ratings - roadway alignment	Better than present minimum criteria [7]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Equal to present minimum criteria [6]
Condition ratings - deck	Fair [5]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	
Pier or abutment protection		Sufficiency rating	85.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends			
Inspection date	May 2011 [0511]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	