

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Missouri [29]	Franklin County [071]	Boles [06958]	S 14 T 43 N R 2 E	38-27-39 = 38.460833	090-46-22 = - 90.772778
15356	Highway agency district 6	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 92	BEND RD	Toll On free road [3]	Features intersected	MERAMEC RVR	
Design - main Steel [3]	Design - approach Wood or timber [7]	Kilometerpoint 8 km = 5.0 mi	Year built 1916	Year reconstructed 1991	
2	Truss - Thru [10]	1	Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared
			Historical significance	Historical significance is not determinable at this time. [4]	
Total length 128.6 m = 421.9 ft	Length of maximum span 61 m = 200.1 ft	Deck width, out-to-out 4.9 m = 16.1 ft	Bridge roadway width, curb-to-curb 4.3 m = 14.1 ft		
Inventory Route, Total Horizontal Clearance 4.3 m = 14.1 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length 1.6 km = 1.0 mi	Method to determine inventory rating	No rating analysis performed [5]	Inventory rating	7 metric ton = 7.7 tons
	Method to determine operating rating	No rating analysis performed [5]	Operating rating	12 metric ton = 13.2 tons
Bridge posting			Design Load	M 9 / H 10 [1]

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	<input type="text" value="Posted for load [P]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - superstructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Good [7]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="2"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="February 2009 [0209]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Unknown [Y60]"/>	Underwater inspection date	<input type="text" value="July 2010 [0710]"/>
Fracture critical inspection	<input type="text" value="Every two years [Y24]"/>	Fracture critical inspection date	<input type="text" value="September 2010 [0910]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>