

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

New Jersey [34] Somerset County [035] Branchburg [07180] NORTH OF THREE BRIDGES RD 40-30-17 = 40.504722 074-45-48 = - 74.763333

18B0511 Highway agency district 2 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 WOODFERN ROAD Toll On free road [3] Features intersected S. BRANCH RARITAN RIVER

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built 1902 Year reconstructed 2006

Skew angle 20 Structure Flared

Historical significance Bridge is eligible for the NRHP. [2]

Total length 31.4 m = 103.0 ft Length of maximum span 30.2 m = 99.1 ft Deck width, out-to-out 4.6 m = 15.1 ft Bridge roadway width, curb-to-curb 4.3 m = 14.1 ft

Inventory Route, Total Horizontal Clearance 4.3 m = 14.1 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Wood or Timber [8]

Type of wearing surface Bituminous [6]

Deck protection

Type of membrane/wearing surface

**Weight Limits**

Bypass, detour length 0.3 km = 0.2 mi Method to determine inventory rating Allowable Stress(AS) [2] Inventory rating 16.3 metric ton = 17.9 tons

Method to determine operating rating Allowable Stress(AS) [2] Operating rating 29 metric ton = 31.9 tons

Bridge posting 00.1 - 09.9 % below [4] Design Load

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Good [7]	Appraisal ratings - roadway alignment	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - substructure	Good [7]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Very Good [8]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	
Pier or abutment protection		Sufficiency rating	48.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	September 2009 [0909]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	September 2009 [0909]
Other special inspection	Every year [Y12]	Other special inspection date	September 2009 [0909]

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

New Jersey [34] Somerset County [035] Hillsborough [31890] NORTH OF THREE BRIDGES RD 40-30-16 = 40.504444 074-45-48 = - 74.763333

18B0512 Highway agency district 2 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 WOODFERN ROAD Toll On free road [3] Features intersected S. BRANCH RARITAN RIVER

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built 1902 Year reconstructed 2006

Skew angle 0 Structure Flared

Historical significance Bridge is eligible for the NRHP. [2]

Total length 25.6 m = 84.0 ft Length of maximum span 25 m = 82.0 ft Deck width, out-to-out 5.5 m = 18.0 ft Bridge roadway width, curb-to-curb 4.7 m = 15.4 ft

Inventory Route, Total Horizontal Clearance 4.7 m = 15.4 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Wood or Timber [8]

Type of wearing surface Bituminous [6]

Deck protection

Type of membrane/wearing surface

**Weight Limits**

Bypass, detour length 0.3 km = 0.2 mi Method to determine inventory rating Allowable Stress(AS) [2] Inventory rating 25.4 metric ton = 27.9 tons

Method to determine operating rating Allowable Stress(AS) [2] Operating rating 39.9 metric ton = 43.9 tons

Bridge posting Equal to or above legal loads [5] Design Load

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Good [7]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Good [7]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Very Good [8]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	
Pier or abutment protection		Sufficiency rating	72.8
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	September 2009 [0909]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	September 2009 [0909]
Other special inspection	Not needed [N]	Other special inspection date	