

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

New York [36]	Rockland County [087]	Orangetown [55211]	1.0 MI N JCT PIP+RTE 303	41-02-44.55 = 41.045708	073-57-29.28 = -73.958133
1068989	Highway agency district: 85	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 0	ORANGEBURG ROAD	Toll On free road [3]	Features intersected	RTE 987C	
Design - main	Concrete [1]	Design - approach		Kilometerpoint	590.5 km = 366.1 mi
1	Arch - Deck [11]	0	Other [00]	Year built	1956
				Year reconstructed	1973
				Skew angle	10
				Structure Flared	Yes, flared [1]
				Historical significance	Historical significance is not determinable at this time. [4]
Total length	27.7 m = 90.9 ft	Length of maximum span	22.8 m = 74.8 ft	Deck width, out-to-out	35.4 m = 116.1 ft
				Bridge roadway width, curb-to-curb	23.8 m = 78.1 ft
Inventory Route, Total Horizontal Clearance	11.9 m = 39.0 ft	Curb or sidewalk width - left	1.5 m = 4.9 ft	Curb or sidewalk width - right	1.5 m = 4.9 ft
Deck structure type	Not applicable [N]				
Type of wearing surface	Bituminous [6]				
Deck protection	Not applicable (applies only to structures with no deck) [N]				
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating		Inventory rating	23.9 metric ton = 26.3 tons
0 km = 0.0 mi	Method to determine operating rating		Operating rating	62.1 metric ton = 68.3 tons
	Bridge posting	Equal to or above legal loads [5]	Design Load	M 18 / H 20 [4]

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - deck	<input type="text" value="Not Applicable [N]"/>		
Scour	<input type="text" value="Bridge not over waterway. [N]"/>		
Channel and channel protection	<input type="text" value="Not applicable. [N]"/>		
Appraisal ratings - water adequacy	<input type="text" value="N/A [N]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="79.9"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="September 2018 [0918]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>