

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26] Calhoun County [025] Marshall [51940] MARSHALL MICHIGAN 42-15-41 = 42.261389 084-57-14 = 84.953889

1417 Highway agency district 5 Owner City or Municipal Highway Agency [04] Maintenance responsibility City or Municipal Highway Agency [04]

Route 0 MARSHALL AVENUE Toll On free road [3] Features intersected KALAMAZOO RIVER

Design - main Concrete [1] Design - approach Other [00] Kilometerpoint 30.7 km = 19.0 mi

1 Arch - Deck [11] 0 Other [00] Year built 1910 Year reconstructed

Skew angle 0 Structure Flared

Historical significance Bridge is not eligible for the NRHP. [5]

Total length 19.5 m = 64.0 ft Length of maximum span 18.9 m = 62.0 ft Deck width, out-to-out 14 m = 45.9 ft Bridge roadway width, curb-to-curb 10.7 m = 35.1 ft

Inventory Route, Total Horizontal Clearance 10.7 m = 35.1 ft Curb or sidewalk width - left 1.2 m = 3.9 ft Curb or sidewalk width - right 0.9 m = 3.0 ft

Deck structure type Not applicable [N]

Type of wearing surface Bituminous [6]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi Method to determine inventory rating Allowable Stress(AS) [2] Inventory rating 14.8 metric ton = 16.3 tons

Method to determine operating rating Allowable Stress(AS) [2] Operating rating 22.2 metric ton = 24.4 tons

Bridge posting Design Load

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Poor [4]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Poor [4]	Appraisal ratings - deck geometry	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - deck	Not Applicable [N]		
Scour	Bridge is scour critical; bridge foundations determined to be unstable. [3]		
Channel and channel protection	Bank and embankment protection is severely undermined. River control devices have severe damage. Large deposits of debris are in the channel. [4]		
Appraisal ratings - water adequacy	Superior to present desirable criteria [9]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	46.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	July 2011 [0711]	Designated inspection frequency	12 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	