

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Pennsylvania [42] Washington County [125] Cecil [11792] 300' NORTH OF SR 4039 40-19-29 = 40.324722 080-14-39 = - 80.244167  
 627206060840070 Highway agency district 12 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route #Num! GALATI ROAD -T608 Toll On free road [3] Features intersected MILLERS RUN

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi  
 1 Truss - Thru [10] 0 Other [00] Year built 1890 Year reconstructed N/A [0000]

Skew angle 0 Structure Flared  
 Historical significance Historical significance is not determinable at this time. [4]

Total length 11 m = 36.1 ft Length of maximum span 10.1 m = 33.1 ft Deck width, out-to-out 4.1 m = 13.5 ft Bridge roadway width, curb-to-curb 3.6 m = 11.8 ft  
 Inventory Route, Total Horizontal Clearance 3.6 m = 11.8 ft Curb or sidewalk width - left 0.2 m = 0.7 ft Curb or sidewalk width - right 0.2 m = 0.7 ft

Deck structure type Open Grating [3]

Type of wearing surface  
 Deck protection  
 Type of membrane/wearing surface

**Weight Limits**

Bypass, detour length 0.5 km = 0.3 mi Method to determine inventory rating Load Factor(LF) [1] Inventory rating 3.6 metric ton = 4.0 tons  
 Method to determine operating rating Load Factor(LF) [1] Operating rating 6.4 metric ton = 7.0 tons  
 Bridge posting Design Load M 13.5 / H 15 [2]

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status

Posted for load [P]

Appraisal ratings -  
structural

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - superstructure

Poor [4]

Appraisal ratings -  
roadway alignment

Equal to present desirable criteria [8]

Condition ratings - substructure

Fair [5]

Appraisal ratings -  
deck geometry

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - deck

Fair [5]

Scour

Bridge is scour critical; bridge foundations determined to be unstable. [3]

Channel and channel protection

Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]

Appraisal ratings - water adequacy

Better than present minimum criteria [7]

Status evaluation

Structurally deficient [1]

Pier or abutment protection

Sufficiency rating

20.9

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

June 2009 [0609]

Designated inspection frequency

24

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Not needed [N]

Fracture critical inspection date

Other special inspection

Unknown [N00]

Other special inspection date