

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Pennsylvania [42]		Allegheny County [003]		Pittsburgh [61000]		301085 BT PHIPPS&S P POOL		40-26-12 = 40.436667		079-56-48 = - 79.946667	
027301000030850		Highway agency district 11		Owner City or Municipal Highway Agency [04]		Maintenance responsibility		City or Municipal Highway Agency [04]			
Route 0		PANTHER HOLLOW TR		Toll On free road [3]		Features intersected PANTH HOLLOW,UNKNOWN STR					
Design - main Steel [3]		Design - approach Masonry [8]		Kilometerpoint 0 km = 0.0 mi		Year built 1896		Year reconstructed 1999			
1 Truss - Deck [09]		4 Arch - Deck [11]		Skew angle 0		Structure Flared					
				Historical significance Bridge is possibly eligible for the NRHP. [3]							
Total length 195.1 m = 640.1 ft		Length of maximum span 109.7 m = 359.9 ft		Deck width, out-to-out 18.6 m = 61.0 ft		Bridge roadway width, curb-to-curb 11.9 m = 39.0 ft					
Inventory Route, Total Horizontal Clearance 8.6 m = 28.2 ft		Curb or sidewalk width - left 2.6 m = 8.5 ft		Curb or sidewalk width - right 2.6 m = 8.5 ft							
Deck structure type		Concrete Cast-in-Place [1]									
Type of wearing surface		Monolithic Concrete (concurrently placed with structural deck) [1]									
Deck protection		Epoxy Coated Reinforcing [1]									
Type of membrane/wearing surface											

Weight Limits

Bypass, detour length 0.6 km = 0.4 mi		Method to determine inventory rating		Load Factor(LF) [1]		Inventory rating 28.1 metric ton = 30.9 tons	
		Method to determine operating rating		Load Factor(LF) [1]		Operating rating 47.2 metric ton = 51.9 tons	
Bridge posting		Equal to or above legal loads [5]		Design Load M 13.5 / H 15 [2]			

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - deck	<input type="text" value="Good [7]"/>		

Scour	<input type="text" value="Countermeasures have been installed to mitigate an existing problem with scour. [7]"/>
-------	--

Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>
--------------------------------	---

Appraisal ratings - water adequacy	<input type="text" value="Superior to present desirable criteria [9]"/>	Status evaluation	<input type="text"/>
------------------------------------	---	-------------------	----------------------

Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="79.5"/>
-----------------------------	----------------------	--------------------	-----------------------------------

Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>
----------	--

Traffic safety features - railings	<input type="text"/>
------------------------------------	----------------------

Traffic safety features - transitions	<input type="text"/>
---------------------------------------	----------------------

Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>
--	--

Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>
---	--

Inspection date	<input type="text" value="May 2009 [0509]"/>	Designated inspection frequency	<input type="text" value="24"/>	Months
-----------------	--	---------------------------------	---------------------------------	--------

Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
-----------------------	---	----------------------------	----------------------

Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
------------------------------	---	-----------------------------------	----------------------

Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>
--------------------------	---	-------------------------------	----------------------