

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Pennsylvania [42]	Elk County [047]	Horton [35816]	700 FT EAST SR 219	41-16-36.48 = 41.276800	078-42-02.88 = -78.700800
15744	Highway agency district: 2	Owner Town or Township Highway Agency [03]	Maintenance responsibility	Town or Township Highway Agency [03]	
Route 0	T-521 PAROLARI RD	Toll On free road [3]	Features intersected	LITTLE TOBY CREEK	
Design - main Concrete [1]	Design - approach Other [00]	Kilometerpoint 0 km = 0.0 mi	Year built 1916	Year reconstructed N/A [0000]	
1	Arch - Deck [11]	Skew angle 0	Structure Flared		
		Historical significance	Bridge is not eligible for the NRHP. [5]		
Total length 14.9 m = 48.9 ft	Length of maximum span 14.9 m = 48.9 ft	Deck width, out-to-out 5.6 m = 18.4 ft	Bridge roadway width, curb-to-curb 4.7 m = 15.4 ft		
Inventory Route, Total Horizontal Clearance 4.7 m = 15.4 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Not applicable [N]				
Type of wearing surface	Not applicable (applies only to structures with no deck) [N]				
Deck protection	Not applicable (applies only to structures with no deck) [N]				
Type of membrane/wearing surface	Not applicable (applies only to structures with no deck) [N]				

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating		Inventory rating 32.7 metric ton = 36.0 tons
	Method to determine operating rating		Operating rating 49 metric ton = 53.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18 / HS 20 [5]

Functional Details

Average Daily Traffic	100	Average daily truck traffi	1	%	Year	2017	Future average daily traffic	125	Year	2037
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	4.3 m = 14.1 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A			Navigation horizontal clearance	0 = N/A					
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft					
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A			Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]					
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	58000	Roadway improvement cost	264000						
	Length of structure improvement	19 m = 62.3 ft		Total project cost	784000					
	Year of improvement cost estimate									
	Border bridge - state					Border bridge - percent responsibility of other state				
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - deck geometry	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - deck	<input type="text" value="Not Applicable [N]"/>		
Scour	<input type="text" value="Bridge is scour critical; bridge foundations determined to be unstable. [3]"/>		
Channel and channel protection	<input type="text" value="Bank and embankment protection is severely undermined. River control devices have severe damage. Large deposits of debris are in the channel. [4]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="60"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="September 2017 [0917]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>