

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Pennsylvania [42]		York County [133]		Spring Grove [73192]		WEST END OF SPRING GROVE		39-52-11 = 39.869722		076-51-52 = - 76.864444	
660116023016600		Highway agency district 8		Owner State Highway Agency [01]		Maintenance responsibility		State Highway Agency [01]			
Route 116		PA 116; SR 0116		Toll On free road [3]		Features intersected CODORUS CREEK					
Design - main Concrete continuous [2]		Design - approach		Kilometerpoint 1501.4 km = 930.9 mi		Year built 1923		Year reconstructed N/A [0000]			
2		Other [00]		0		Other [00]		Skew angle 0		Structure Flared	
						Historical significance Bridge is not eligible for the NRHP. [5]					
Total length 41.1 m = 134.8 ft		Length of maximum span 19.5 m = 64.0 ft		Deck width, out-to-out 8 m = 26.2 ft		Bridge roadway width, curb-to-curb 7.2 m = 23.6 ft					
Inventory Route, Total Horizontal Clearance 7.2 m = 23.6 ft		Curb or sidewalk width - left 1.5 m = 4.9 ft		Curb or sidewalk width - right 0 m = 0.0 ft							
Deck structure type		Concrete Cast-in-Place [1]									
Type of wearing surface		Bituminous [6]									
Deck protection											
Type of membrane/wearing surface		Preformed Fabric [2]									

Weight Limits

Bypass, detour length 0.5 km = 0.3 mi		Method to determine inventory rating		Load Factor(LF) [1]		Inventory rating 42.6 metric ton = 46.9 tons	
		Method to determine operating rating		Load Factor(LF) [1]		Operating rating 63.5 metric ton = 69.9 tons	
Bridge posting		Equal to or above legal loads [5]				Design Load	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - superstructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Bridge is scour critical; bridge foundations determined to be unstable. [3]"/>		
Channel and channel protection	<input type="text" value="Bank and embankment protection is severely undermined. River control devices have severe damage. Large deposits of debris are in the channel. [4]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present minimum criteria [6]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="44"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="August 2009 [0809]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Every two years [Y24]"/>	Underwater inspection date	<input type="text" value="September 2003 [0903]"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>