

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Pennsylvania [42]		Cumberland County [041]		Silver Spring [70792]		SILVER SPRING TWP		40-12-09.80 = 40.202722		077-02-32.83 = -77.042453	
14024		Highway agency district: 8		Owner State Toll Authority [31]		Maintenance responsibility		State Toll Authority [31]			
Route 641		SR 641, LR 507		Toll On free road [3]		Features intersected PA TPK (I-76)					
Design - main Steel [3]		Design - approach		Kilometerpoint 4560.7 km = 2827.6 mi		Year built 1949		Year reconstructed N/A [0000]			
1 Girder and floorbeam system [03]		0 Other [00]		Skew angle 44		Structure Flared					
				Historical significance Bridge is not eligible for the NRHP. [5]							
Total length 36.3 m = 119.1 ft		Length of maximum span 35.1 m = 115.2 ft		Deck width, out-to-out 15.2 m = 49.9 ft		Bridge roadway width, curb-to-curb 12.2 m = 40.0 ft					
Inventory Route, Total Horizontal Clearance 10.4 m = 34.1 ft		Curb or sidewalk width - left 1.5 m = 4.9 ft		Curb or sidewalk width - right 0.4 m = 1.3 ft							
Deck structure type		Concrete Cast-in-Place [1]									
Type of wearing surface		Monolithic Concrete (concurrently placed with structural deck) [1]									
Deck protection											
Type of membrane/wearing surface											

Weight Limits

Bypass, detour length 0.5 km = 0.3 mi		Method to determine inventory rating		Load Factor(LF) [1]		Inventory rating 34.5 metric ton = 38.0 tons	
		Method to determine operating rating		Load Factor(LF) [1]		Operating rating 58.1 metric ton = 63.9 tons	
Bridge posting		Equal to or above legal loads [5]		Design Load MS 18 / HS 20 [5]			

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge not over waterway. [N]		
Channel and channel protection	Not applicable. [N]		
Appraisal ratings - water adequacy	N/A [N]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection		Sufficiency rating	80.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	February 2017 [0217]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	February 2017 [0217]
Other special inspection	Not needed [N]	Other special inspection date	