

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Tennessee [47]	Warren County [177]	Unknown [00000]	GREAT FALLS DAM	35-48-06.00 = 35.801667	085-37-18.00 = -85.621667
890A2490001	Highway agency district 2	Owner County Highway Agency [02]	Maintenance responsibility	Tennessee Valley Authority [67]	
Route 249	A249	Toll On free road [3]	Features intersected	CANEY FORK RIVER	
Design - main Steel [3]	Design - approach Steel [3]	Kilometerpoint 0 km = 0.0 mi	Year built 1925	Year reconstructed 1931	
18	Stringer/Multi-beam or girder [02]	9	Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared
			Historical significance	Bridge is possibly eligible for the NRHP. [3]	
Total length 238.4 m = 782.2 ft	Length of maximum span 9.1 m = 29.9 ft	Deck width, out-to-out 4.7 m = 15.4 ft	Bridge roadway width, curb-to-curb	4.4 m = 14.4 ft	
Inventory Route, Total Horizontal Clearance 4.4 m = 14.4 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft		
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection	Other [9]				
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	4.4 metric ton = 4.8 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	7.4 metric ton = 8.1 tons
Bridge posting		Design Load		

Functional Details

Average Daily Traffic	25	Average daily truck traffi	0	%	Year	2011	Future average daily traffic	65	Year	2032
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	4.6 m = 15.1 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	2500000	Roadway improvement cost	100000						
	Length of structure improvement	239.3 m = 785.1 ft		Total project cost	2600000					
	Year of improvement cost estimate	2005								
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Posted for load [P]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - superstructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - deck	<input type="text" value="Good [7]"/>		
Scour	<input type="text" value="Bridge foundations (including piles) on dry land well above flood water elevations. [9]"/>		
Channel and channel protection	<input type="text" value="Not applicable. [N]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Superior to present desirable criteria [9]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="30"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="August 2012 [0812]"/>	Designated inspection frequency	<input type="text" value="12"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>