

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Texas [48]	Williamson County [491]	Unknown [00000]	0.8 MI N OF FM 1466	30-28-11.54 = 30.469872	097-22-54.25 = -97.381736
142460AA0410001	Highway agency district: 14	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 456	CR 456	Toll On free road [3]	Features intersected	BRUSHY CREEK	
Design - main Steel [3]	Design - approach	Kilometerpoint 128.7 km = 79.8 mi	Year built 1912	Year reconstructed 2005	
1 Truss - Thru [10]	0 Other [00]	Skew angle 0	Structure Flared		
		Historical significance	Bridge is eligible for the NRHP. [2]		
Total length 42.7 m = 140.1 ft	Length of maximum span 41.5 m = 136.2 ft	Deck width, out-to-out 5.4 m = 17.7 ft	Bridge roadway width, curb-to-curb 4.8 m = 15.7 ft		
Inventory Route, Total Horizontal Clearance 4.8 m = 15.7 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection	Unknown [8]				
Type of membrane/wearing surface	Unknown [8]				

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	0 metric ton = 0.0 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	0 metric ton = 0.0 tons
	Bridge posting		Design Load	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Bridge closed to all traffic [K]	Appraisal ratings - structural	
Condition ratings - superstructure	Critical [2]	Appraisal ratings - roadway alignment	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Equal to present minimum criteria [6]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]		
Channel and channel protection	Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]		
Appraisal ratings - water adequacy	Equal to present minimum criteria [6]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	28.2
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Not applicable or a safety feature is not required. [N]		
Traffic safety features - transitions	Not applicable or a safety feature is not required. [N]		
Traffic safety features - approach guardrail	Not applicable or a safety feature is not required. [N]		
Traffic safety features - approach guardrail ends	Not applicable or a safety feature is not required. [N]		
Inspection date	December 2017 [1217]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	June 2015 [0615]
Other special inspection	Not needed [N]	Other special inspection date	