

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Texas [48]	Bexar County [029]	San Antonio [65000]	0.3 MI W OF BROADWAY AVE.	29-26-40.03 = 29.444453	098-28-53.79 = -98.481608
150150B14515001	Highway agency district: 15	Owner City or Municipal Highway Agency [04]	Maintenance responsibility City or Municipal Highway Agency [04]		
Route 0	E GRAYSON ST	Toll On free road [3]	Features intersected SAN ANTONIO RIVER		
Design - main Concrete [1]	Design - approach	Kilometerpoint 45.1 km = 28.0 mi	Year built 1929	Year reconstructed N/A [0000]	
2 Tee beam [04]	0 Other [00]	Skew angle 16	Structure Flared		
		Historical significance	Bridge is possibly eligible for the NRHP. [3]		
Total length 26.8 m = 87.9 ft	Length of maximum span 13.4 m = 44.0 ft	Deck width, out-to-out 19.5 m = 64.0 ft	Bridge roadway width, curb-to-curb 13.4 m = 44.0 ft		
Inventory Route, Total Horizontal Clearance 13.4 m = 44.0 ft	Curb or sidewalk width - left 2.4 m = 7.9 ft	Curb or sidewalk width - right 2.4 m = 7.9 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection	Unknown [8]				
Type of membrane/wearing surface	Unknown [8]				

**Weight Limits**

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	No rating analysis or evaluation perfor	Inventory rating	24.5 metric ton = 27.0 tons
	Method to determine operating rating	No rating analysis or evaluation perfor	Operating rating	32.7 metric ton = 36.0 tons
Bridge posting	Equal to or above legal loads [5]		Design Load	

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Other structural work, including hydraulic replacements. [38]

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Good [7]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]		
Channel and channel protection	Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]		
Appraisal ratings - water adequacy	Better than present minimum criteria [7]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection		Sufficiency rating	70.4
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	July 2017 [0717]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	