

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Texas [48]	Collingsworth County [087]	Unknown [00000]	9.17 MI E OF US 83	34-53-15.17 = 34.887547	100-03-07.57 = -100.052103
250440023001006	Highway agency district: 25	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 203	SH 203	Toll On free road [3]	Features intersected	SALT FORK OF RED RIV	
Design - main Steel [3]	Design - approach Steel [3]	Kilometerpoint 1460.8 km = 905.7 mi	Year built 1939	Year reconstructed 2014	
4	Truss - Thru [10]	1	Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared
		Historical significance		Bridge is on the NRHP. [1]	
Total length 229.5 m = 753.0 ft	Length of maximum span 54.6 m = 179.1 ft	Deck width, out-to-out 8.2 m = 26.9 ft	Bridge roadway width, curb-to-curb 7.3 m = 24.0 ft		
Inventory Route, Total Horizontal Clearance 7.3 m = 24.0 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection	Unknown [8]				
Type of membrane/wearing surface	Unknown [8]				

Weight Limits

Bypass, detour length 5.5 km = 3.4 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	25.4 metric ton = 27.9 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	41.7 metric ton = 45.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	M 13.5 / H 15 [2]	

Functional Details

Average Daily Traffic	180	Average daily truck traffi	19	%	Year	2013	Future average daily traffic	260	Year	2033
Road classification	Major Collector (Rural) [07]		Lanes on structure	2		Approach roadway width	6.7 m = 22.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	4.65 m = 15.3 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	834000	Roadway improvement cost	209000						
	Length of structure improvement	241.7 m = 793.0 ft		Total project cost	1043000					
	Year of improvement cost estimate									
	Border bridge - state					Border bridge - percent responsibility of other state				
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - deck	<input type="text" value="Good [7]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present minimum criteria [6]"/>	Status evaluation	<input type="text"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="71.8"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Not applicable or a safety feature is not required. [N]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="August 2017 [0817]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Every two years [Y24]"/>	Fracture critical inspection date	<input type="text" value="July 2016 [0716]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>